


Figure#1 – Simple Fiber Cable Change Example



Figure#2 – Example Implementation of Software Components

BEST AVAILABLE COPY




Figure #3 – Complex Fiber Cable Change Example




Figure #4 – NMS Window Showing Miscabling Correlation




Figure #5 – NMS Window Identifying Cross-connects Impacted




Figure #6 – NMS Window Identifying Lightpaths Impacted